

L Number	Hits	Search Text	DB	Time stamp
1	2514	310/166.cccls. or 310/168.cccls. or 310/68b.cccls.	USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/03/16 15:39
2	504	(310/166.cccls. or 310/168.cccls. or 310/68b.cccls.) and (rotor same (slot or hole or opening or cavity or perforation))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/03/16 15:39
3	1420	318/\$.cccls. and (rotor same (slot or hole or opening or cavity or perforation))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/03/16 15:40
-	1165	310/268.cccls.	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/01/21 12:34
-	170	310/264.cccls.	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/09/07 14:56
-	2495	310/261.cccls.	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/09/07 14:56
-	1456	310/40r.cccls.	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/09/07 14:56
-	391	310/10.cccls.	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/09/07 15:02
-	10	((310/264.cccls. or 310/261.cccls. or 310/40r.cccls. or 310/10.cccls.) and ((rotor near (flat or circular))and control\$3)) not 310/268.cccls.	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/01/21 12:41
-	23	310/268.cccls. and ((rotor near (flat or circular))and control\$3)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/09/07 15:03
-	2	("4568862" "4578610").PN.	USPAT	2002/09/07 15:12
-	13	("3334254" "3418506" "3823919" "4121668" "4169983" "4358693" "4371801" "4382190" "4392073" "4503349" "4521349" "4792237" "4804439").PN.	USPAT	2002/09/07 15:20
-	7	("4074157" "4303843" "4318019" "4475075" "4639626" "4798986" "4866321").PN.	USPAT	2002/09/07 15:21
-	24	("3223867" "3225235" "3355914" "3735231" "4081726" "4288709" "4315171" "4316394" "4353602" "4483570" "4514674" "4677327" "4683391" "4737753" "4761574" "4794286" "4857782" "4922145" "5160877" "5198711" "5216308" "5237229" "5334894" "5396140").PN.	USPAT	2002/09/07 15:23
-	30	(310/268.cccls. or 310/264.cccls. or 310/261.cccls. or 310/40r.cccls. or 310/10.cccls.) and @pd>20020907	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/10/09 10:41
-	987	((rotor near (flat or circular))and control\$3)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/10/09 10:41
-	391	((rotor near (flat or circular))and control\$3)) and slot	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/01/21 12:47

-	6861	vehicle and (brake and rotor)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/01/21 12:48																																				
-	1107	(vehicle and (brake and rotor)) and slot	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/10/09 10:42																																				
-	21	(US-6342769-\$ or US-6283255-\$ or US-6244391-\$ or US-6161660-\$ or US-5921354-\$ or US-5915504-\$ or US-5915505-\$ or US-4868443-\$ or US-5039895-\$ or US-5117141-\$ or US-5696419-\$ or US-5959382-\$ or US-4798986-\$ or US-4866321-\$ or US-6509663-\$ or US-3355914-\$ or US-4081726-\$ or US-4288709-\$ or US-3862289-\$ or US-3867656-\$ or US-6472784-\$).did.	USPAT	2003/10/09 10:40																																				
-	6	((US-6342769-\$ or US-6283255-\$ or US-6244391-\$ or US-6161660-\$ or US-5921354-\$ or US-5915504-\$ or US-5915505-\$ or US-4868443-\$ or US-5039895-\$ or US-5117141-\$ or US-5696419-\$ or US-5959382-\$ or US-4798986-\$ or US-4866321-\$ or US-6509663-\$ or US-3355914-\$ or US-4081726-\$ or US-4288709-\$ or US-3862289-\$ or US-3867656-\$ or US-6472784-\$).did.) and commutat\$3	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/10/09 10:43																																				
-	48	(310/268.ccls. or 310/264.ccls. or 310/261.ccls. or 310/40r.ccls. or 310/10.ccls.) and @pd>20030121	USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/03/12 10:28																																				
-	31	((rotor near (flat or circular))and control\$3)) and @pd>20030121	USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/03/12 10:29																																				
-	52	((vehicle and (brake and rotor)) and slot) and @pd>20030121	USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/03/12 10:29																																				
-	21	((310/268.ccls. or 310/264.ccls. or 310/261.ccls. or 310/40r.ccls. or 310/10.ccls.) and @pd>20030121) or (((rotor near (flat or circular))and control\$3)) and @pd>20030121) or ((vehicle and (brake and rotor)) and slot) and @pd>20030121)) and commutat\$3	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/10/09 10:51																																				
-	34	<table border="1"> <tr><td>"0530717"</td><td>"1465251"</td><td>"2408080"</td></tr> <tr><td>"2409600"</td><td>"2845554"</td><td>"2914688"</td></tr> <tr><td>"3084269"</td><td>"3133216"</td><td>"3185877"</td></tr> <tr><td>"3270228"</td><td>"3465187"</td><td>"3488533"</td></tr> <tr><td>"3594596"</td><td>"3616761"</td><td>"3699370"</td></tr> <tr><td>"3705995"</td><td>"3736450"</td><td>"3784853"</td></tr> <tr><td>"3944865"</td><td>"3989969"</td><td>"4021690"</td></tr> <tr><td>"4097758"</td><td>"4321499"</td><td>"4372633"</td></tr> <tr><td>"4514653"</td><td>"4677334"</td><td>"4691133"</td></tr> <tr><td>"4866321"</td><td>"5451825"</td><td>"5481149"</td></tr> <tr><td>"5514923"</td><td>"5866967"</td><td>"5923114"</td></tr> <tr><td colspan="3">"6049150").PN.</td></tr> </table>	"0530717"	"1465251"	"2408080"	"2409600"	"2845554"	"2914688"	"3084269"	"3133216"	"3185877"	"3270228"	"3465187"	"3488533"	"3594596"	"3616761"	"3699370"	"3705995"	"3736450"	"3784853"	"3944865"	"3989969"	"4021690"	"4097758"	"4321499"	"4372633"	"4514653"	"4677334"	"4691133"	"4866321"	"5451825"	"5481149"	"5514923"	"5866967"	"5923114"	"6049150").PN.			USPAT	2003/10/09 10:54
"0530717"	"1465251"	"2408080"																																						
"2409600"	"2845554"	"2914688"																																						
"3084269"	"3133216"	"3185877"																																						
"3270228"	"3465187"	"3488533"																																						
"3594596"	"3616761"	"3699370"																																						
"3705995"	"3736450"	"3784853"																																						
"3944865"	"3989969"	"4021690"																																						
"4097758"	"4321499"	"4372633"																																						
"4514653"	"4677334"	"4691133"																																						
"4866321"	"5451825"	"5481149"																																						
"5514923"	"5866967"	"5923114"																																						
"6049150").PN.																																								
-	31	(310/268.ccls. or 310/264.ccls. or 310/261.ccls. or 310/40r.ccls. or 310/10.ccls.) and @pd>20031009	USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/03/12 10:29																																				
-	19	((rotor near (flat or circular))and control\$3)) and @pd>20031009	USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/03/12 10:30																																				
-	32	((vehicle and (brake and rotor)) and slot) and @pd>20031009	USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/03/12 10:31																																				

-	84780	rotor same (slot or hole or opening or cavity or perforation)	USPAT; EPO; JPO; DERWENT; IBM TDB	2004/03/16 15:39
-	12379	(rotor same (slot or hole or opening or cavity or perforation)) and (stator same (coil or winding))	USPAT; EPO; JPO; DERWENT; IBM TDB	2004/03/12 10:36
-	4810	((rotor same (slot or hole or opening or cavity or perforation)) and (stator same (coil or winding))) and (disk or flat)	USPAT; EPO; JPO; DERWENT; IBM TDB	2004/03/12 10:38
-	3780	((rotor same (slot or hole or opening or cavity or perforation)) and (stator same (coil or winding))) and (disk or flat)) and (position or location)	USPAT; EPO; JPO; DERWENT; IBM TDB	2004/03/12 10:40
-	1943	((((rotor same (slot or hole or opening or cavity or perforation)) and (stator same (coil or winding))) and (disk or flat)) and (position or location)) and 310/\$.ccls.	USPAT; EPO; JPO; DERWENT; IBM TDB	2004/03/12 10:42